User Selection Criteria

Location: NEW JERSEY
Handler ID: NJD060728060

Evaluation Date Range: From: 10/01/1990 To: 08/02/2021

Report Results

Number of Handlers: 1 Number of Pages: 3

Report Description

This report provides a complete listing of evaluation, violation and enforcement activities for each handler, including all orphan records. Below the handler id information, the data is presented in three sections; evaluations, violations and enforcements. Notes are provided in each respective section.

3007 Information Requests that are not linked to an evaluation will appear below the handler universe information. 3007 Information Requests that are linked to an evaluation will appear below the evaluation information within the light blue section.

Last Updated On: 04/09/2021

Comprehensive Compliance Monitoring and Enforcement Report

Page 2

BUCKEYE RARITAN BAY TERMINAL

County MIDDLESEX / NJ023

NJD060728060 Region: 02

Location 577 SMITH ST, PERTH AMBOY, NJ 08861

Latitud 40.511853 Longitude -74.290536

Mailing: 577 SMITH ST, PERTH AMBOY, NJ 08861

Activity No	J	State District: CE	NTRAL	Accessibility		Non-		Extract Flag: Y	Active Site: Y	
Generator:	LQG	Operating TSDF:		Offsite Receiver	: N	State Unadd	ressed SNC:	N	EPA Unaddressed SNC:	N
Short Term Generate	or: N	Transporter:	N	IC in Place:	N	State Addres	sed SNC:	N	EPA Addressed SNC:	N
Full Enforcement:		Transfer Facility:	N	El Indicator (HE	/GW): N / N	State SNC w	/Comp Sched	d: N	EPA SNC w/Comp Sched:	N
CA Wrkld:	N	Converter:		HSM:	N					
Active State Gen:	Υ	State TSDF:		Subpart K:						
CEI Evaluation	06/01/2012	Activity Location:	NJ By:	STATE	Identifier:	001 Person:	coscc	Suborganization:	Found Violation	: NO
NOC Date: Citizen Complaint: NO Multimedia Inspection: NO Sampling: NO Not Subtitle C: NO Day Zero: 06/01/2012 Focus Area: Eval. Notes: Hess First Reserve Terminal was considered an LQG of hazardous waste due to large shipments of hazardous waste occasionally generated by the facility, though no hazardous waste was found to be on site during the inspection. The inspection was conducted as a routine inspection and to investigate an Unmanifested Waste report submitted by Cycle Chem in Elizabeth (NJD002200046) on										ound to
	5/5/11 for a nor	hazardous waste shipm	ent from the facility t	hat was found to flash	below 140 degre	es F. No stewardship activ	ities were ide	ntified by the facility	or noted for the site. Hess First	:
									e and distribution facility compos	sed of
	•	` `	,,,	•	,	rack and associated transf		,	es/garage/boiler building, esene, light cycle oil, diesel, No.	6 oil cat
									il, diesel, kerosene only). Hazar	
									nnually (D006/D007) and other	
	•	•	· ·		,		,	9	e includes batteries, lamps and	
	consumer elect	ronics, which are sent to	veolia facilities for r	ecycling (last shipped l	March 2012). No	nhazardous water from tar	ik cleaning (w	nen not work is nec	essary at a tank) is	

No Linked Violations

CEI Evaluation	12/15/2009	Activity Location:	NJ	Ву:	STATE	Identifier:	001	Person:	COMLE	Suborganization:	C F	Found Violation:	NO
NOC Date):	Citizen Complaint:	NO	Multimedia Inspection	n: NO	Sampling:	NO	Not Subtitle C:	NO	Day Zero:	12/15/2009	Focus Area:	

No Linked Violations

Note: Penalty information associated with an enforcement action is reported with the enforcement action. For enforcement actions associated with multiple violations, the penalty information will be reported with each violation, however, the penalty is only assessed once, regardless of the number of violations associated with the enforcement.

Comprehensive Compliance Monitoring and Enforcement Report

Page 3

BUCKEYE RARITAN BAY TERMINAL - continued NJD060728060												28060
CEI Evaluation	01/20/2006	Activity Location:	NJ	Ву:	STATE	Identifier:	001	Person:	SOMWH	Suborganization:	C Found Violation:	NO
NOC Date:		Citizen Complaint:	NO	Multimedia Inspe	ction: NO	Sampling:	NO	Not Subtitle C:	NO	Day Zero:	Focus Area:	
Eval. Note	s:											

No Linked Violations